

2011 North Dakota Flooding Photos

April 11th, 2011

Argusville, Harwood, and Fargo in the distance



Hillsboro Sub

Flying over the Hillboro near Argusville



I-29 closed

Hillsboro Sub

Hillsboro sub and I-29 Near Harwood



Hillsboro Sub



Interstate 29



Harwood, ND

Clay dike across Hillsboro protecting Harwood. This is the reason for the closure of the subdivision.



Fargo, ND





Devils Lake Sub


Looking WB at the Devils Lake near MP 180



Washout at MP 180.3



Approximately 70' suspended. We are adding 3 culverts at this location.



Mouse River bridge at MP 162.6 near Towner, ND



Devils Lake sub near Towner, ND. Flooding in this are is caused by Mouse River.





Mouse River Bridge MP 163.8 west of Towner

Devils Lake at Churches Ferry. This is bridge MP 103.6.



Highway bridge at Grand Forks, ND

Flood wall



Red River out of its banks south of Grand Forks

Normal River Width

